



Known Issues
- LINUS Control v2.1.18 -





1. Known Issues

Key	Components	Description	Workaround	Fixed in
#1208	LINUS 14/	2WAY Preset routing and tuning parameters are	If using Amplifiers in standalone mode, IE no LINUS	
	LINUS CON	not linked together between channels on Front	Control, if 2WAY preset is used, routing, gain, delay &	
		Panel when in standalone mode.	other filters need to be applied individually to both	
			channels of the loudspeaker.	
#1213	LINUS Control	MacOS Firewall can sometimes prevent LC	Disable MacOS Firewall.	
		connection to the network, even with LC		
		nominated as an 'Allowed' App. It typically will		
		allow LC to connect, but if LC is closed, then re-		
		opened, connections may not be possible.		
#1263	LINUS5-C	When a LINUS5-C or LINUS10-C speaker	Press and hold the channel MUTE buttons to see the	
	LINUS10-C	assignment is changed on the front panel, the	loudspeaker assignments.	
		text string on the LCD is not updated with the		
		new assignments.		
#1256	LINUS14-D	There is no logic implemented w.r.t Dante	Patch the same signal to both loudspeaker components	
		patching on 2WAY loudspeaker presets.	in Dante Controller.	
		IE it is possible to patch a different signal to the		
		LF and HF component of the same 2WAY pair.		
#1218	LINUS Control	It is not possible to restore a show file from the	Keep backup / safety copies of show files on removable	
		networked LINUS Amplifiers.	media.	
#1279	LINUS Control	If a LINUS-C device is batch replaced with a		
		L14/CON/10 that has fallback enabled, the LINUS-		
		C will try to assume fallback, but it will fail.		
#1276	LINUS Control	Amplifier protection state is reported unreliably		
		in LINUS Control.		
#1265	LINUS5-C /	Front panel network LED's can be seen to flash		
	LINUS10-C	briefly every few seconds.		
#1214	LINUS 14/	Front Panel LCD does not report the correct serial	Check the sticker on the rear of the amplifier to	
	LINUS CON /	number.	determine the amplifier serial number.	
	LINUS 10			



2. Fixed Issues

2.1.Fixed in v2.1.18:

Key	Components	Description	Workaround	Fixed in
#1216	LINUS	Front Panel LCD reports "LINUS LIVE ONLINE" and		V2.1
	Amplifiers	"LINUS LIVE OFFLINE" rather than "LINUS		
		CONTROL ONLINE" and "LINUS CONTROL		
		OFFLINE".		
#1215	LINUS Control	After updating firmware on LINUS 14 / CON / 10	Power Cycle the amplifiers after the Firmware Update	V2.1
	/LINUS 14/	in LINUS Control, they may reappear in the	process is complete & this error will be cleared.	
	LINUS CON /	discovery list, stating that they need the		
	LINUS 10	Firmware Updating (again).		
#1217	LINUS Control	If a 2-byte language is selected for Operating		V2.1
	v2.0.34	System, the text of some messages may be		
		clipped in the application window.		
#1240	LINUS Control	Input meter data is drawn incorrectly on the		V2.1
	v2.0.34	workspace on LINUS14-D's when using Dante, if		
		the input routing matrix is not set to ABCD.		
#1210	LINUS	If power is lost within a couple of seconds of a		V2.1
	Amplifiers	new loudspeaker being selected on an amplifier		
		channel, or changing a snapshot, the state of the		
		amplifier does not persist when the power was		
		restored.		
#1268	LINUS Control	LINUS Control may incorrectly report that the IP		V2.1
	v2.0.34	address of the computer is incorrectly set, when		
		multiple network adapters are enabled on the		
		host machine.		
#1219	LINUS Control	When more that 36 LINUS10's are present on the		V2.1
	v2.0.34	network, connections appear to be unstable,		
		with seemingly random amplifiers showing as		
		red or 'disconnected' on the workspace.		
#1045	LINUS Control	Recover Fallback button text blocks button press.	Click above or below the text on the Recover Digital	V2.1
	v2.0.34		button.	
#1048	LINUS Control	LINUS5-C and LINUS10-C can in some edge cases		V2.1
	v2.0.34	show the incorrect input meters in the input		
		meter view within the LC workspace.		
#1233	LINUS Control	If LINUS Control is 'Locked' in monitor mode, and	Delete 'state.json' and restart software	V2.1
	v2.0.34	then the software is closed without unlocking the		
		interface, the locked state will persist into the		
		new workspace when the application is		
		relaunched.		
#1160	LINUS Control	ViRAY, APS-SUB and U4 can be assigned to a		V2.1
	v2.0.34	LINIUS5-C in breach of assignments law.		
#1295	LINUS Control	Workspace horizontal and vertical scrollbars are		V2.1
	v2.0.34	always shown, regardless if they are needed or		
		not.		
#1139	LINUS Control	Mouse click and drag on PEQ and other tuning		V2.1
	v2.0.34	tools sometimes do not respond until click		
		release.		
#1292	LINUS Control	LC Crashes if server>>GUI communication port is		V2.1
	v2.0.34	in use by another OS process, or a hung LC start.		
#1250	LINUS Control	Identify tool does not work if any groups are		V2.1
	v2.0.34	selected.		
#1246	LINUS Control	Tuning window size is forgotten when window is		V2.1
	v2.0.34	dismissed.		
#1220	LINUS Control	User is prompted to save show file when LC is		V2.1
	v2.0.34	closed, even if there are no unsaved changes.		
#1222	LINUS Control	If the Array tool is not available in a group, it is		V2.1
		shown as 8x, rather than N/A which is confusing.		



#1289	LINUS Control	When batch replacing amplifiers, text string on	Change the input view to speakers view by pressing '4'	V2.1
	v2.0.34	destination amplifier can block the destination	on the keyboard.	
		button.		
#1278	LINUS Control	Amplifier output meters on workspace can		V2.1
	v2.0.34	sometimes be seen to reach 'full-scale'		
		prematurely.		
#1243	LINUS Control	Rounding error within tuning groups can lead to		V2.1
	v2.0.34	0.1dB mismatch between tuning group gain		
		indication and amplifier state.		
#1239	LINUS Control	Input matrix assignment dropdown list draws		V2.1
	v2.0.34 on	with light-grey text on a white background,		
	Windows	which is hard to read.		
#1253	LINUS10-C/	Metering bug with routing set to AABB or CCDD		V2.1
	LINUS5-C	etc in LINUS Control.		
#1235	LINUS Control	When adding lots of amplifiers to the workspace,		V2.1
	v2.0.34	in some circumstances they can be added on top		
		of each other, in the top left position on the		
		workspace.		
#1194	LINUS Control	Group data not always re-pushed to amplifier		V2.1
	v2.0.34	when loudspeaker type changed.		
#1176	LINUS Control	LINUS 10 in AMPS page is displayed as a 4x		V2.1
	v2.0.34	Channel amplifier, not a 2x channel amplifier		
#1135	LINUS Control	If you click and drag the PEQ points around in the		V2.1
	v2.0.34	tuning graph, if you pass outside the bounds of		
		the graph, text elements of the application can		
		be selected.		
#1134	LINUS Control	With more than circa 60 amplifiers connected to		V2.1
	v2.0.34	the network, the GUI can slow down		
		considerably.		
#1060	LINUS Control	LINUS14 meters draw at half of the speed of		V2.1
	v2.0.34	LINUS10 meters.		
#1288	LINUS	LINUS10-C does not respond to *GET UDP		V2.1
		Commands		
#1280	LINUS14	LiNET Fallover too sensitive. It falls to analog		V2.1
		when one sample of audio is lost.		
#1260	LINUS10	Cannot set channel routing from front panel of		V2.1
		LINUS10.		
#1257	LINUS	It is possible to load empty snapshots from the		V2.1
	Amplifiers	front panel, which puts the amplifier into an		
		unknown state.		
#1302	LINUS10-C	L10-C and L5-C LIMIT LEDs may latch ON with no		V2.1
	LINUS5-C	limiter activity after typically 7 days of continued		
		use.		