



Known Issues
- LINUS Control v2.2.33 -





1. Known Issues

Key	Components	Description	Workaround	Fixed in
#1208	LINUS 14/	2WAY Preset routing and tuning parameters are	If using Amplifiers in standalone mode, IE no LINUS	
	LINUS CON	not linked together between channels on Front	Control, if 2WAY preset is used, routing, gain, delay &	
		Panel when in standalone mode.	other filters need to be applied individually to both	
			channels of the loudspeaker.	
#1213	LINUS Control	MacOS Firewall can sometimes prevent LC	Disable MacOS Firewall.	
		connection to the network, even with LC		
		nominated as an 'Allowed' App. It typically will		
		allow LC to connect, but if LC is closed, then re-		
		opened, connections may not be possible.		
#1263	LINUS5-C	When a LINUS5-C or LINUS10-C speaker	Press and hold the channel MUTE buttons to see the	
	LINUS10-C	assignment is changed on the front panel, the	loudspeaker assignments.	
		text string on the LCD is not updated with the		
		new assignments.		
#1256	LINUS14-D	There is no logic implemented w.r.t Dante	Patch the same signal to both loudspeaker components	
		patching on 2WAY loudspeaker presets.	in Dante Controller.	
		IE it is possible to patch a different signal to the		
		LF and HF component of the same 2WAY pair.		
#1276	LINUS Control	Amplifier protection state is reported unreliably		
		in LINUS Control.		
#1265	LINUS5-C/	Front panel network LED's can be seen to flash		
	LINUS10-C	briefly every few seconds.		
#1266	LINUS5-C/	Unit Lock disables Front panel mute buttons		
	LINUS10-C			
#72	LINUS5-C/	Analog signal source is activated when loading	Use LINUS Control to activate correct analog fallback	
	LINUS10-C	snapshot on LINUS5-C/ 10-C frontpanel with	functionality	
		activated analog fallback.		
#81	LINUS Control	LINUS Control Application launch after	Security setting might not let LINUS Control start up at	
#01	LINOS CONTION	installation on Mac OS	its first launch, a security waring is displayed. Click with	
			the right mouse button on the LINUS Control App in	
			your application folder and select "Open" and again	
			"Open" in the security warning. This needs to be done	
#100	LINILIC Combin	De celline Chate frame man della cellina di cel	only at the first application launch.	
#100	LINUS Control	Recalling State from modules with activated analog fall back and assigning activates analog	Disconnect and reconnect digital signal source. Recover digital is now possible. This happens only when	
		fallback source. Recover digital source not	modules had the Analog signal source routing before	
		possible. Same behavior at recalling setup files.	recall of state and setup file	
		,		



2. Fixed Issues

2.1. Fixed in v2.2.14:

Key	Components	Description	Workaround	Fixed in
#1218	LINUS Control	It is not possible to restore a show file from the		V2.2.14
		networked LINUS Amplifiers.		
#1214	LINUS 14/	Front Panel LCD does not report the correct serial		V2.2.14
	LINUS CON /	number.		
	LINUS 10			
#1306	LINUS5-C/	Cannot lock / unlock LINUS10-C or 5-C with Front	Unlock possible from Front Panel.	V2.2.14
	LINUS10-C	Panel.	Use LC to lock 5-C and 10-C.	
#1308	LINUS14	If an amplifier has fallback ON, and is power-		V2.2.14
		cycled, when it restarts, it will jump to Analog,		
		even if digital signal was present throughout.		
#1305	LINUS14/	With the device front panels locked, if the mute		V2.2.14
	LINUS CON /	buttons are pressed, they will take effect when		
	LINUS10	the device is unlocked again.		
#gh29	LINUS	3 rd Party UDP Commands *GET_GAIN &		V2.2.14
	Amplifiers	*GET_DELAY are addressed 03 rather than 14		
#gh49	LINUS	Analog Fallback Source partially inherited the		V2.2.14
	Amplifiers	analog routing. All initialised to A now.		
#1316	LINUS Control	Dismissing the tablet entry popup doesn't enable		V2.2.14
		the parameter.		
#1262	LINUS14	Fans 'hunt' during idle operation.		V2.2.14

2.2. Fixed in v2.1.30:

Key	Components	Description	Workaround	Fixed in
#1347	LINUS Control	Array tuning tool had no effect when set above		V2.1.30
		20x. Limited to 20x.		
#1332	LINUS Control	Input & Output metering sometimes covered by		V2.1.30
		other elements within amplifier display.		
#1331	LINUS Control	Adding a new PEQ to group would take too long		V2.1.30
		to show if it is already in use.		
#1330	LINUS Control	Amplifier Limit & meter backgrounds can flash		V2.1.30
		and persist on the screen when the amplifiers are		
		dragged around the workspace		
#1329	LINUS Control	Opening a group on some machines can cause		V2.1.30
		'ghosted' group assignments to be shown on the		
		amplifier channels.		
#1327	LINUS Control	Windows only – 'File\Open Recent' list could		V2.1.30
		sometimes be empty.		
#1326	LINUS Control	Workspace zoom slider would not be drawn in		V2.1.30
		the correct place when a showfile was loaded		
		with the zoom slider not in the centre.		
#1324	LINUS Control	When a showfile is loaded, all amplifiers are		V2.1.30
		returned to the 'virtual' state, rather than		
		'disconnected'.		
#1323	LINUS Control	Monitor Mode – monitor pane - 'left' and 'right'		V2.1.30
		scroll arrows scroll the amplifiers in the incorrect		
		order.		
#1321	LINUS Control	Clicking a group mute in Tune mode would		V2.1.30
		present the tuning pane, when it shouldn't.		



#1313	LINUS Control	Remote Access should be able to be disabled.	V2.1.30
		New enable / disable access implemented, see	
		new features list.	
#1312	LINUS Control	Replace IP pane would only launch if virtual	V2.1.30
		amplifiers are selected, not disconnected	
		amplifiers.	
#1311	LINUS Control	CMD+F Shortcut could add more than 254x	V2.1.30
		amplifiers.	
#1310	LINUS Control	CMD+F Shortcut would always add a LINUS14,	V2.1.30
		not the amplifier type chosen in the speakers bar.	
#1307	LINUS Control	Some 'special characters' – EG "/ >" would cause	V2.1.30
		amplifiers to disconnect if they were entered	
		within the amplifiers 'Name' field.	
#1297	LINUS Control	Tuning parameters that are not active appear	V2.1.30
		active due to their text colour. Text colour	
		changed when parameter is inactive.	
#1279	LINUS Control	If a LINUS-C device is batch replaced with a	V2.1.30
		L14/CON/10 that has fallback enabled, the LINUS-	
		C will try to assume fallback, but it will fail.	
		Fallback has now been implemented in LINUS-C.	
#1280	LINUS14	LiNET Fallover to Analog too sensitive.	

2.3. Fixed in v2.1.18:

Key	Components	Description	Workaround	Fixed in
#1216	LINUS Amplifiers	Front Panel LCD reports "LINUS LIVE ONLINE" and "LINUS LIVE OFFLINE" rather than "LINUS CONTROL ONLINE" and "LINUS CONTROL OFFLINE".		V2.1.18
#1215	LINUS Control / LINUS 14 / LINUS CON / LINUS 10	After updating firmware on LINUS 14 / CON / 10 in LINUS Control, they may reappear in the discovery list, stating that they need the Firmware Updating (again).	Power Cycle the amplifiers after the Firmware Update process is complete & this error will be cleared.	V2.1.18
#1217	LINUS Control v2.0.34	If a 2-byte language is selected for Operating System, the text of some messages may be clipped in the application window.		V2.1.18
#1240	LINUS Control v2.0.34	Input meter data is drawn incorrectly on the workspace on LINUS14-D's when using Dante, if the input routing matrix is not set to ABCD.		V2.1.18
#1210	LINUS Amplifiers	If power is lost within a couple of seconds of a new loudspeaker being selected on an amplifier channel, or changing a snapshot, the state of the amplifier does not persist when the power was restored.		V2.1.18
#1268	LINUS Control v2.0.34	LINUS Control may incorrectly report that the IP address of the computer is incorrectly set, when multiple network adapters are enabled on the host machine.		V2.1.18
#1219	LINUS Control v2.0.34	When more that 36 LINUS10's are present on the network, connections appear to be unstable, with seemingly random amplifiers showing as red or 'disconnected' on the workspace.		V2.1.18
#1045	LINUS Control v2.0.34	Recover Fallback button text blocks button press.	Click above or below the text on the Recover Digital button.	V2.1.18
#1048	LINUS Control v2.0.34	LINUS5-C and LINUS10-C can in some edge cases show the incorrect input meters in the input meter view within the LC workspace.		V2.1.18
#1233	LINUS Control v2.0.34	If LINUS Control is 'Locked' in monitor mode, and then the software is closed without unlocking the	Delete 'state.json' and restart software	V2.1.18



#1278	LINUS Control	Amplifier output meters on workspace can	V2.1.18
# 1270	v2.0.34	sometimes be seen to reach 'full-scale'	V2.11.10
		prematurely.	
#1243	LINUS Control	Rounding error within tuning groups can lead to	V2.1.18
	v2.0.34	0.1dB mismatch between tuning group gain indication and amplifier state.	
#1239	LINUS Control	Input matrix assignment dropdown list draws	V2.1.18
	v2.0.34 on	with light-grey text on a white background,	
	Windows	which is hard to read.	
#1253	LINUS10-C / LINUS5-C	Metering bug with routing set to AABB or CCDD etc in LINUS Control.	V2.1.18
#1235	LINUS Control	When adding lots of amplifiers to the workspace,	V2.1.18
	v2.0.34	in some circumstances they can be added on top	
		of each other, in the top left position on the workspace.	
#1194	LINUS Control	Group data not always re-pushed to amplifier	V2.1.18
	v2.0.34	when loudspeaker type changed.	
#1176	LINUS Control	LINUS 10 in AMPS page is displayed as a 4x	V2.1.18
	v2.0.34	Channel amplifier, not a 2x channel amplifier	
#1135	LINUS Control	If you click and drag the PEQ points around in the	V2.1.18
	v2.0.34	tuning graph, if you pass outside the bounds of	
		the graph, text elements of the application can	
#1124	LINILIS Control	be selected. With more than circa 60 amplifiers connected to	\/2 1 10
#1134	LINUS Control v2.0.34	With more than circa 60 amplifiers connected to the network, the GUI can slow down	V2.1.18
	V2.U.34	the network, the GUI can slow down considerably.	
#1060	LINUS Control	LINUS14 meters draw at half of the speed of	V2.1.18
,,,,,,,,,	v2.0.34	LINUS10 meters.	· Z.1.10
#1288	LINUS	LINUS10-C does not respond to *GET UDP	V2.1.18
		Commands	
#1280	LINUS14	LiNET Fallover too sensitive. It falls to analog	 V2.1.18
#1262	LINILICAC	when one sample of audio is lost.	1/2 1 1 2
#1 16()	LINUS10	Cannot set channel routing from front panel of	V2.1.18
#1260		LINUS10.	
#1257	LINUS	LINUS10. It is possible to load empty snapshots from the	V2.1.18



#1302	LINUS10-C	L10-C and L5-C LIMIT LEDs may latch ON with no	V2.1.18
	LINUS5-C	limiter activity after typically 7 days of continued	
		use.	